

**MUMBAI PORT TRUST**  
**PORT DEPARTMENT**

No. DC/C-NM/ 4130

DATE-27.09.2010.

**LOCAL NOTICE TO MARINER NO.05 OF 2010**  
**INDIA WEST COAST - MUMBAI HARBOUR.**

-----

IT IS REPORTED THAT-

1) SUSPECTED UNDERWATER OBSTRUCTION IN POSITION LAT 18°: 53.548 'N AND / LONG. 072°: 51.216'E MARKED WITH SYNTHETIC BUOY 1 METERHIGH ( A QUICK FLASHING YELLOW LIGHT ) REPORTED UNLIT. ALL MARINERS TO TAKE NOTE, NAVIGATE WITH CAUTION AND AVOID MANEOUVRING IN CLOSE PROXIMITY.

2) DIVING OPERATOINS TO RETRIVE POSSIBLE SUNKEN CONTAINER IN POSITION LAT 18: 53.548'N / LONG 072: 51.216' E (OFF B2) WILL BE UNDERTAKEN BETWEEN 07.30 HRS.& 09.30HRS. ON 28<sup>TH</sup> SEPTEMBER 2010. ALL MARINERS TO TAKE SERIOUS NOTE AND PROCEED WITH EXTERMELY SLOW SPEED. THERE WILL BE NO NAVIGATION ALLOWED WITHIN 0.5 NAUTICAL MILE DURING THE PERIOD.

3) DIVING OPERATIONS TO RETRIVE POSIBLE SUNKEN CONTAINER IN POSITION LAT. 18: 53.548'N/ LONG. 072: 51.216 E (OFF B2) WILL BE UNDERTAKEN BETWEEN 08.00HRS. AND 1000 HRS. ON 29 SEPTEMBER. ALL MARINERS TO TAKE SERIOUS NOTE AND PROCEED WITH EXTERMELY SLOW SPEED. THERE WILL BE NO NAVIGATION ALLOWED WITHIN 0.5 NAUTICAL MILE DURING THE PERIOD.

ALL VESSELS APPROACHING OR DEPARTING MUMBAI HARBOUR ARE HEREBY WARNED TO KEEP A SHARP LOOKOUT AND NAVIGATE WITH CAUTION.

**HARBOUR MASTER**