दुरध्वनी: 6656 5480

Tel: 6656 5480

Email idoffice@mumbaiport.gov.in



विराष्ट उप यातायात प्रबंधक, इंदिरा गोदी तिसरी मंजिल, आंबेडकर भवन, इंदिरा गोदी निल द्वार के पास, मंबई: 400001.

Sr. Dy. Traffic Manager, Indira Dock Mumbai Port Authority 3rd Floor, AmbedkarBhavan, P.D'Mello Road, Nr.Blue Gate, ID. Mumbai – 400 001.

No. TM/ID/Dock Safety/ 7

of 2024-25

1 5 APR 2024

CIRCULAR No. 10

Docks Local Transporter & Lorry Owners Associations.
The President, Association of Multimodal Transport Operators of India
The President, Indian Merchant Chambers
The President All India Liquid Bulk Importers & Exporters Association
Secretary Maharashtra Rajya Motor Malak Sangh
The President, Maharashtra Truck Owner's Association
Mumbai Nava Sheva Godi Motor Malak Sangh

Sirs,

Sub: Standard Operating Procedure (SOP) for the Transportation of CR/HR coils in Mumbai Port Authority premises.

Vide Circular No. TM/S/1/41 of 22-23 dated 18.11.2022, it was requested to inform your members for strict compliance of the SOP for transportation of CR/HR coils in Mumbai Port Authority premises to prevent any untoward incident and loss of human life.

- 2. Further, vide Circular No. TM/ID/ Docks Safety/ 2425 of 2022-23 dated 29.03.2023, it was once again requested to inform your members as under
 - 1) for strict compliance of the SOP

Mumbai Malvahatuk Tempo Mahasangh

- 2) The coils shall be transported in the trailers with appropriate lashing in MbPA premises in a safe manner.
- 3. It is however, observed that some of the transporters are not complying the abovesaid SOP which may endanger the life and safety of Dock workers.
- 4. In view of above, it is once again requested to inform all your members to strictly comply with the abovesaid SOP in the subject matter. Any non-compliance to the above shall be viewed seriously and action as deem fit shall be taken against defaulters.

Yours faithfully,

Sr. Dy. Traffic Manager Operation Docks